

## ZAŁĄCZNIK NR 1

L.P.	Oznaczenie	Norma	Klasa	RAZEM SZT
			śruby	
1	HVM16*55	6914	10.9	36
2	MU16	6915	10	52
3	SCHEIBE17	6916	St	104
4	HVM16*60	6914	10.9	16
5	HVM20*65	6914	10.9	24
6	MU20	6915	10	24
7	SCHEIBE21	6916	St	48
8	HVM24*75	6914	10.9	24
9	MU24	6915	10	24
10	SCHEIBE25	6916	St	48
11	M12*40	82101	8.8	4
12	NAKRETKA_M12	82144	St	156
13	PODKLADKA13	82005	St	312
14	M12*45	82101	8.8	96
15	M16*50	82101	8.8	10
16	NAKRETKA_M16	82144	St	2050
17	PODKLADKA17	82005	St	4100
18	M16*55	82101	8.8	12
19	M16*60	82101	8.8	58
20	M16*70	82101	8.8	2
21	U-SCHEIBE13	6918	C45	8
22	U-SCHEIBE17	6918	C45	2
23	M20*70	82101	8.8	4
24	NAKRETKA_M20	82144	St	468
25	PODKLADKA21	82005	St	936
26	PNM12*50	82101	8.8	48
27	PNM12*60	82101	8.8	8
28	PNM 16*50	82001	8.8	272
29	PNM16*55	82101	8.8	50
30	PNM 16*60	82001	8.8	254
31	PNM 16*65	82001	8.8	1168
32	PNM 16*70	82101	8.8	152
33	PNM 16*80	82101	8.8	72
34	MU24	82144	ST	160
35	PODKŁADKA SAMOKLINUJĄCA HEICO HLK M24			160
36	MU36	82144	ST	20
37	PODKŁADKA SAMOKLINUJĄCA HEICO HLK M36			20
38	PNM 20*60	82101	8.8	152
39	PNM 20*70	82001	ST	120
40	PNM 20*75	82101	8.8	22
41	PNM 20*80	82101	8.8	40
42	PNM 20*85	82101	10.9	130
43	SPM16*170	1480	ST35	76
44	MU30	555	5	192
45	RING30	125	ST	96
46	PNM 30*110	82101	10.9	78
47	NAKRETKA_M30	82144	St	6
48	PODKLADKA 31	82005	St	12

PNM-śruba z niepełnym gwintem

SKG-śruba z pełnym gwintem

SPM-nakrętka napinająca "śruba rzymska "

HVM-śruby do połączeń sprężanych kl 10.9

MU16-nakrętka dla śruby fi 16 mm

SCHEIBE17- podkładka dla śruby fi 16